


AIRPORT DIAGRAM

AL-322 (FAA)

PHOENIX SKY HARBOR INTL (PHX)

PHOENIX, ARIZONA

SW-4, 10 JAN 2013 to 07 FEB 2013



A SDE-X Surveillance System in use. Pilots should operate transponders with Mode C on all twys and rwys.

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES. ANNUAL RATE OF CHANGE READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED. 0.1° W

RWYS 07L-25R, 07R-25L, 08-26 S-30, D-200, 25-17.5, 2B-400, 2D/2D2-620

AIRPORT DIAGRAM

PHOENIX SKY HARBOR INTL (PHX)

PHOENIX, ARIZONA

SW-4, 10 JAN 2013 to 07 FEB 2013